


# Assembly Instruction




Hammer and Screwdriver  
are not included !!




NO.	QTY.	LINEDRAWING
(A)	50	
(B)	50	
(C)	2	
(D)	11	
(E)	20	
(F)	51	
(G)	19	
(H)	5	
(I)	12	
(J)	8	
(K)	8	
(L)	1	
(M)	4	

# PARTS LIST




NO.	QTY.	NO.	QTY.
①	1	⑫	1
②	1	⑬	1
③	1	⑭	1
④	1	⑮	1
⑤	1	⑯	1
⑥	1	⑰	1
⑦	5	⑱	1
⑧	5	⑲	1
⑨	5	⑳	1
⑩	5	㉑	2
⑪	5	㉒	2

1




H		F	
5x		20x	

2




A		B	
4x		4x	

3




D	
4x	

4




I		R	
4x		1x	



5




D  
4x




7




B  
8x




A  
8x



6




I  
4x




8



K  
8x




D  
3x






A  
4x



B  
4x





9





11





10





5x






12







13




A		B	
	12x		12x



15



G	
	19x

14



M		I	
	4x		4x