










# Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	36	
(B)	36	
(C)	24	
(D)	4	
(E)	36	

   
Hammer and Screwdriver  
are not included !!




# PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	1
⑩	1
⑪	1
⑫	1

1




A	B
6x	6x
C	J
4x	6x

2




A	B
4x	4x
C	J
4x	4x

3




A	B
4x	4x
C	J
4x	4x





4




A	B
12x	12x
C	J
4x	12x

5





A  10x	B  10x
C  8x	J  10x

7



6



H 
4x