

## **Pretreatment**

Ensure surfaces to be bonded are clean and free of dust, grease or oil. Pooled water should be removed. Substrates must be stable. Remove any contaminants likely to impair adhesion. Before application, mask off the adjacent area with foil or tape, if necessary. Check paint or coatings are firmly attached, if not remove it. Apply adhesive onto one of the surfaces: 1) In spots in order to smooth uneven surfaces, 2) in wave-like form for higher initial tack with wide surfaces or 3) in straight strands for smaller surfaces. In case of outdoor use, apply vertical beads. Important in case of 2 non-absorbent surfaces: Adhesive must not form continuous areas as contact with air/moisture is necessary for adhesive setting. Make sure the adhesive beads do not merge. When fully cured UniBond No More Nails All Materials Crystal can be painted, water-based acrylic paints are particularly suitable. It is recommended to test the compatibility of a coating product before use. Oxygen curing paints (e.g. alkyd-resin) show longer drying/tackiness. 2K-Epoxy paints show bad levelling property. Fresh adhesive may be cleaned with a cloth soaked in a solvent (alcohol or white spirit). Once fully cured, No More Nails Crystal can only really be removed by mechanical means (i.e. a chisel or similar tool).

- Shelf life 10 months from date of production if stored in unopened original tubes, in dry conditions and protected from direct sunlight at temperatures between +5°C and 25°C.
  
- If medical advice is needed, have product container or label at hand. Keep out of reach of children. Do not get in eyes, on skin, or on clothing. Use only outdoors or in a well-ventilated area.