



DRAUGHT SEAL TAPE

1. Ensure surfaces to be taped are dry and free from grease, dust and debris.
2. Apply tape along the length of gaps and cracks. Cut to length with scissors, allowing at least 25mm tape beyond the end of the gap. Press tape firmly into place.
3. If a gap is visible both outside and inside it is advisable to apply tape on both sides to achieve best results.