










Assembly Instruction



Hardware List


<p>A</p>  <p>X8</p>	<p>B</p>  <p>X20</p>	<p>C</p>  <p>X28</p>
<p>D</p>  <p>X10</p>	<p>E</p>  <p>X28</p>	<p>F</p>  <p>X28</p>
<p>G</p>  <p>X2</p>		<p>H</p>  <p>X2</p>

J




X1

K




X1





Parts List




1




2




3




4




5




6




7



8



9



10

