




CHANDLER



30'




1

Beliani

1/11

Beliani
T761/CHANDLER/051223/

A	B	C	D	E	F
x 1	x 1	x 1	x 1	x 1	x 1



G	H	I	J	K	L
x 1	x 2	x 4	x 1	x 2	x 2

2/11

Beliani
T761/CHANDLER/051223/

M	N	O
		 M3.5 x 16
x 10	x 10	x 16





P	Q	R
 M6 x 35		
x 10	x 1	x 2

S1	S2	T
	 M3 x 12	
x 2	x 2	x 8

U	V
	
x 1	x 4

3/11

Beliani
T761/CHANDLER/051223/







4/11

Beliani
T761/CHANDLER/051223/

5/11

Beliani
T761/CHANDLER/051223/







6/11

Beliani
T761/CHANDLER/051223/

7/11

Beliani
T761/CHANDLER/051223/






8/11

Beliani
T761/CHANDLER/051223/

9/11

Beliani
T761/CHANDLER/051223/



10/11

Beliani
T761/CHANDLER/051223/

11/11

Beliani
T761/CHANDLER/051223/