









ASSEMBLY INSTRUCTION











HARDWARE

A	 M6x28	04
B	 M6x45	28
C	 M6	28

D		01
E		01




01








B	 M6X45	08
C	 M6	08
D		01
E		01

02

2x









B	 M6X45	04
C	 M6	04
E		01

A	 M6X28	04
D		01




03


2x





B	 M6X45	16
C	 M6	16
D		01
E		01



ASSEMBLY INSTRUCTION







HARDWARE





A	 M6x45	34
B	 M6	34

C		01
D		01




01





2x



A	 M6X45	04
B	 M6	04
C		01
D		01



02



A	 M6X45	14	C		01
B	 M6	14	D		01



03



2x






A	M6X45	16
B	M6	16
C		01
D		01



ASSEMBLY INSTRUCTION








HARDWARE





A		12
B		08
C		08

D		01
E		01



01







02



03



B	 M6X45	08
C	 M6	08
D		01
E		01

04

